



# Instrument Firmware Release Notes

## Models

DS4012, DS4014, DS4022, DS4024, DS4032, DS4034, DS4052, DS4054, MSO4012, MSO4014, MSO4022, MSO4024, MSO4032, MSO4034, MSO4052, MSO4054

## Version Information

Released version: 00.02.02.03.05

Release Date: 5/1/2015

## Compatibility

Compatible with earlier versions of the hardware

## Change Log

Key:

E – Enhancements. Changes that add functionality

M – Modifications. Changes to improve performance on existing features

C – Cancellation. Removal of function or capability

\*Note: Engineering change log is translated from engineering documentation

Version : 00.02.02.03.05		Date : 2015-04-08
1.	Modify the message hint for the license and firmware installing window	M
2.	Improve the friendliness of the license installing and updating menu	M
3.	Fixed the bug of SCPI GPIB communication	M
4.	Fixed the bug of SCPI USB communication	M
5.	Fixed the data fetching of the decoder	M
6.	Supporting the license file installed by U DISK	E
7.	Supporting the upgrading of bandwidth by license	E
8.	Supporting the decoder of multi-modules license file	E
9.	Fixed the data fetching of the decoder	M
10.	Fixed the crashing problem of high-res mode sampling	M
11.	Fixed the status error of reading ASCII format memory data	M
12.	Fixed the crashing problem of adjusting the offset in the slow scan mode.	M

Version : 00.02.02.01.01		Date : 2014-10-10
1.	Added the function and menu support for T2R1000	E
2.	Added the function and menu support for RP7000S	E
3.	Added the label for Math	E
4.	Added RMS measure of n cycle	E
5.	Added phase and delay measure of different edge	E
6.	Added menu languages for German, Portuguese, Japanese, Korean and Polish	E
7.	Create shortcut menu in decoder.	E
8.	The wave can't refresh when opening and closing measure statistics repeatedly.	M
9.	The menu can't refresh after opening wave zoom when STOP	M
10.	The menu are wrong after inserting the active probe.	M
11.	The Measure value are not refresh after changing the thresholds when STOP	M
12.	The wfm is wrong, when loading from ROLL mode.	M
13.	The record will play back by Navigation buttons after ending record	M
14.	The wave will be offset when adjusting the delay calibration and rest the horizontal offset after STOP	M
15.	The navigation buttons adjust the current frame when the ending frame is selected	M
16.	The items of phase measure will refresh when sources are changed	M
17.	The deviation values are wrong sometimes	M
18.	The LA frequency counter will be the quarter of the original value when STOP	M
19.	The record interval time did not work well.	M
20.	The waveform is error while opening channel in 'Wait' status.	M
21.	Fixed the RS232 decode error while switching memory depth during delay mode.	M

22.	Fixed the crush issue of delay screen in vernier timebase while main screen in slow mode.	M
23.	Update LXI driver	M
24.	While the IIC trigger type is data, the trigger status is influenced by IIC address.	M
25.	Adjusting LA offset in STOP, the waveform of analog channel changed.	M
26.	Use the browser manual IP successfully changed, executed after initialization crashing	M
27.	System crash when track NONE.	M
28.	SCPI commands (WAVEform:SOURce) support logic channels	M
29.	Fixed the blurred screen problem	M

<b>Version : 00.02.01.00.03</b>		<b>Date : 2013-11-29</b>
1.	Fixed the crash issue when the length of decode overflow in binary format	M
2	Optimize the operation speed of MSO model	E
3.	Fixed the crash issue when switching time base mode during zoom mode	M
5	Optimized software to increase the storage speed of PNG format	E
4.	Fixed the crash issue when switching wave size of LA	M

<b>Version : 00.02.00.00.04</b>		<b>Date : 2013-07-30</b>
1.	Fixed measure jitter at some particular freq	M
2.	Optimized the wave intensity in zoom mode	E
3.	Decreased the default brightness of grid	E
4.	Optimized socket communication(201302000018)	E
5.	Fixed wave data error by continues SCPI command	M
6.	Fixed cursor display error when switch track mode form auto mode(201303000024)	M

7.	Fixed the problem of waveform freezing when decode function is activated.	M
8.	Solved the abnormal waveform problem of MSO4000 in vernier timebase.	M
9.	Fixed the MSO4000 crash issue when using default function in XY mode.	M
10.	Solved the abnormal waveform problem when vernier timebase greater than 100ms.	M
11.	Fixed the crash issue when using AUTO function.	M
12.	Fixed the crash issue when fetching image remotely	M

<b>Version : 00.01.00.00.06</b>		<b>Date : 2013-01-08</b>
13.	Optimized the speed of PNG file storage	E
14.	Added SCPI command for channel delay-cal(:chan1:tcal? )	E
15.	Added SCPI command for pattern trigger.( :TRIGger:PATtern:SOURce?)	E
16.	Fixed the data error of .csv file	M
17.	Increased the sampling rate in ROLL mode	E
18.	Optimized the algorithm of AUTO setup	M
19.	Merged the latest LXI module which support socket protocol	E
20.	Modified the priority of trigger channel after auto setup	M
21.	Added some SCPI commands including REF setup FlexRay trigger and channel delay calibration	E
22.	Incorporated the MSO module to firmware at first time	E
23.	Optimized the compatibility for updated flash chip and writing/reading speed	E
24.	Optimized the trace display in normal trigger mode when change the horizontal or vertical setting	M
25.	Switched the position of channel in XY mode	M
26.	Fixed the trigger issue which is CANNOT trigger in CAN data trigger	M
27.	Fixed the SCPI issue which is the vertical scale cannot set rightly by	M

	SCPI command when probe ratio is not 1X	
--	---	--

## End of Change Log History

For more information in North America, please go to [rigolna.com](http://rigolna.com), contact us directly at [techsupport@rigol.com](mailto:techsupport@rigol.com) or call us toll free at **877-4-RIGOL-1**.

### **Rigol Technologies USA**

10200 SW Allen Blvd, Suite C  
Beaverton, OR 97005  
877.474.4651

For more information in Europe, please go to [rigol.eu](http://rigol.eu), contact us directly at [applications-europe@rigoltech.com](mailto:applications-europe@rigoltech.com) or call us **+49 89 89 41 895-0**.

### **Rigol Technologies EU GmbH**

Lindberghstr. 4  
82178 Puchheim, Germany  
+49 89 89 41 895 - 0