

A14 board pulled proud of the chassis for a little poking around.

Switch for the "preset" position.

Channel A&B level pots.

A12 Amp board.

K5 relay repaired.

This trimmer cap seemed to be shorted but was not. Some sneaky inductors on the board acted like shorts when poked.

