

Resin has been applied with a toothpick to all exposed sides. It seems to have taken to the surrounding surfaces very well and cured within a minute under the UV lamp. These knobs have taken a beating for sure. You need to zoom in pretty close to see things clearly.

Note the dislocated brass insert.

I think I could mix me up some putty colored Testers and pretty much make this seam go away.

