



Figure 2. Dc current - equipment setup.

Table 5. Dc Current Accuracy

Test instrument		Dc current shunt
RANGE pushbuttons (MA)	Indications (MA)	Range plug settings (A)
100 $\mu$ A	100.00 $\mu$ A	.0001
10	10.000	.01
100	100.00	.1
1000	1000.0	1