

Here's the signal count out of the 8656A. This is not a real special frequency counter obviously, but I have to say I was surprised by the read out. If the HP is doing 50 MHz out to 3 decimal places, I think I can work with that on the type of projects I work on. I'm sure, metrology wise, there's a lot wrong here, but I'm just tickled that the sig gen seems to be doing what it does pretty well.



Only slightly less accuracy was observed down to 10 KHZ.