

T17 solder joints
look strange, but
transistor seems
ok

T18 complete short

T13 complete short

T14 complete short

T15 complete short

T21 complete short


Thermal switch -->
closed contact

T20 already
removed by me,
seems ok

T3 solder joints seem to have gotten hot.

T9 solder joints seem to have gotten hot.

bodge SMD transistor T1 from someones previous repair ?



C32 / R_BURN1

C22 / R_BURN